Oil Field Environmental Incident Summary

Responsible Party: STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: BROWN 30-19 #2H

Field Name: ALGER Well File #: 20790

Date Incident:3/20/2015Time Incident:09:30Facility ID Number:County:MOUNTRAILTwp: 156Rng: 93Sec: 31Qtr:

Location Description:

Submitted By: David Killingsworth Received By:

Contact Person: David Killingsworth

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 2 Barrels 2 Barrels 2 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/1/2016 Clean Up Concluded: 4/28/2015

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

topsoil off location

Action Taken or Planned:

The pipeline was shut in and clean up crew dispatched to location. Routine inspections of location and equipment.

Wastes Disposal Location: PDI

Agencies Involved:

Updates

Date: 3/20/2015 Status: Reviewed - Follow-up Required Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a valve/piping connection leak impacted topsoil off location. Followup is necessary. Called report contact to determine extent and location of impacted topsoil due to possible agricultural well located just west of the pad. Contact will check with field personnel. Contact called back and said release was on north side of wellpad ~20 ft off the pad. Based on aerial photography, this should be away from the possible well.

Date: 5/8/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 4/28/2015.

Minimal impacts to areas off of location. Site has been remediated, and there are no signs of impact.

No followup is necessary.